

Technisches Datenblatt



Produkt: DP105

Hersteller: 3M DEUTSCHLAND GMBH

Warengruppe: KLEBSTOFF

Artikelgruppe: 2-K KLEBSTOFF

Download: 28.03.2024

SCOTCH-WELD™ DP105

Dieses Datenblatt wurde Ihnen von der Firma tewipack Uhl GmbH zur Verfügung gestellt. Die Firma tewipack Uhl GmbH übernimmt keinerlei Verantwortung für die Aktualität und die Richtigkeit der enthaltenen Informationen. Die Eigenschaften der Produkte können sich aufgrund verschiedener Einflüsse wie beispielsweise Zusammensetzung und Zustand des Substrats, Unreinheiten in oder auf dem Substrat, Temperatur und Luftfeuchtigkeit bei der Lagerung und Umgebungsbedingungen während der Anwendung ändern. Bei Verwendung dieses Produkts in Kombination mit anderem Material ist der Kunde dafür verantwortlich, durch eigene Tests zu prüfen, ob das Produkt für die geplante Kombination geeignet ist und ob diese Kombination die erwarteten Ergebnisse liefert

3M

Scotch-Weld™

Epoxy Adhesives

DP-105 Clear

Technical Data

September, 1998

(Supersedes February, 1993)

Product Description

Available in larger containers as Scotch-Weld™ Epoxy Adhesives 105 B/A Clear.

DP-105 Clear Epoxy Adhesive is a fast setting, very flexible 1:1 mix ratio epoxy adhesive/sealant. Its flexibility when cured makes it ideal for applications involving dissimilar surfaces where thermal coefficient of expansion may be a problem. It is also unique in that it retains its clear, colorless properties even when cured in larger masses where many clear epoxy systems will often turn amber from the reaction exotherm.

Features

- 4 minute worklife
- Flexible
- Clear
- High peel strength
- 1:1 mix ratio

Typical Uncured Physical Properties

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

Product		DP-105 Clear
Base Resins		Epoxy/Mercaptan
Color	Base (B) Accelerator (A)	Clear Clear
Net Weight (Lbs./Gallon)	Base (B) Accelerator (A)	9.3 9.6
Viscosity ¹ , Approximate @ 80°F (27°C)	Base (B) Accelerator (A)	2,000 cps 11,000 cps
Mix Ratio (B:A)	By Volume By Weight	1:1 1:0.97
Worklife ² @ 73°F (23°C)	2 gram 20 gram	5 minutes 4 minutes

Scotch-Weld™

Epoxy Adhesives

DP-105 Clear

Typical Cured Properties

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

	DP-105 Clear
Physical	
Color	Clear
Hardness Shore D (ASTM D 2240)	39
Worklife²	3-4 minutes
Tackfree Time³	10 minutes
Time to Handling Strength⁴	20 min. @ 23°C (73°F)
Cure Time⁵	48 hrs. @ 23°C (73°F)
Elongation⁶	120%
Tensile Strength⁶	600 psi

Thermal	
Weight Loss by Thermal Gravimetric Analysis (TGA)⁷	1% @ 117°C (243°F) 5% @ 289°C (552°F)
Thermal Coefficient of Expansion (TCE) by TMA⁸ ($\infty \times 10^{-6}$ units/unit/°C) Below Tg Above Tg	— 181 (40-140°C range)
Glass Transition Temperature (Tg) by DSC⁹ Onset Mid-Point	8°C (46°F) 15°C (59°F)
Thermal Conductivity¹⁰ (@ 110°F on .250" samples) BTU-ft./ft. ² - hr.-°F Cal./sec -cm-°C Watt/m-°C	.085 .35 x 10 ⁻³ .147
Thermal Shock Resistance¹¹ Potted Washer Olyphant Test (3M/AdhD Test Method C-3174 +100°C [air] to -50°C [liquid])	Pass 5 cycles without cracking

Electrical	
Dielectric Constant @ 1 KHz @ 23°C (73°F) [ASTM D 150]	9.2
Dissipation Factor @ 1 KHz @ 23°C (73°F) [ASTM D 150]	0.22
Dielectric Strength (ASTM D 149) Sample Thickness Approx. 30 mil	465 volts/mil
Volume Resistivity (ASTM D 257)	1.5 x 10 ¹⁰ ohm-cm

Scotch-Weld™

Epoxy Adhesives

DP-105 Clear

Typical Adhesive Performance Characteristics

The following product performance data was obtained in the 3M laboratory under the conditions specified. The following data show typical results obtained with the Scotch-Weld adhesives when applied to properly prepared substrates, cured, and tested according to the specifications indicated. This data was generated using the EPX™ Applicator System equipped with an EPX static mixer, according to manufacturer's directions. Thorough hand mixing should afford comparable results.

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

	DP-105 Clear
Overlap Shear (OLS) to¹² (Bonds aged 24 hrs @ RT + 2 hrs @ 160°F (71°C))	
Etched Aluminum	2000 psi
Sanded Aluminum (60 grit)	1500 psi
Cold Rolled Steel	1300 psi
Wood, Fir	300 psi
Glass, Borosilicate	200 psi
Glass, +3M 3901 Primer	250 psi
Polycarbonate	400 psi
Acrylic	250 psi
Fiberglass	1400 psi
ABS	300 psi
PVC	520 psi
Polypropylene	80 psi

Rate of Strength Buildup (OLS on Etched Aluminum) ¹² Bonds tested after:	
1 hr @ RT	250 psi
6 hrs @ RT	500 psi
24 hrs @ RT	1000 psi
7 days @ RT	2000 psi
1 mo @ RT	2000 psi

Environmental Aging (OLS on Etched Aluminum) ¹² Bonds tested after:	
24 hrs RT + 2 hrs @ 160°F (71°C)	2000 psi
24 hrs RT + 2 hrs @ 240°F (116°C)	2200 psi
1 wk RT + 1 wk @ 90°F/90% RH	1800 psi
1 wk RT + 1 wk 248°F (120°C)	3000 psi

Scotch-Weld™

Epoxy Adhesives

DP-105 Clear

Typical Adhesive Performance Characteristics (continued)

	DP-105 Clear
Overlap Shear Strength vs Temperature¹² (Bonds cured 24 hr @ RT + 2 hrs @ 160°F [71°C]) Bonds tested at:	
-67°F (-53°C)	3500 psi
70°F (21°C)	2000 psi
120°F (49°C)	400 psi
150°F (66°C)	250 psi
180°F (82°C)	150 psi

180° Peel Strength vs Temperature¹³ (Bonds cured 24 hr @ RT + 2 hrs @ 160°F [71°C]) Bonds tested at:	
-67°F (-53°C)	3.0 piw
70°F (21°C)	35.0 piw
120°F (49°C)	5.0 piw
150°F (66°C)	2.0 piw
180°F (82°C)	1.0 piw

Solvent Resistance¹⁴	One Hour/One Month
Acetone	A/A
Isopropyl Alcohol	A/A
Freon TF	A/A
Freon TMC	A/B
1,1,1 Trichloroethane	A/A
RMA Flux	A/A
Key: A - Unaffected, B - Slight Attack, C - Moderate/Severe Attack	

Exotherm¹⁵	Max. Temp/Time to Reach
2 gram mass	98°F (37°C)/5 min.
20 gram mass	230°F (110°C)/3 min.

Scotch-Weld™

Epoxy Adhesives

DP-105 Clear

Handling/Curing Information

Directions for Use

1. For high strength structural bonds, paint, oxide films, oils, dust, mold release agents and all other surface contaminants must be completely removed. However, the amount of surface preparation directly depends on the required bond strength and the environmental aging resistance desired by user. For specific surface preparations on common substrates, see the following section on Surface Preparation.
2. Uses gloves to minimize skin contact. **Do not** use solvents for cleaning hands.
3. Mixing

For Duo-Pak Cartridges

Scotch-Weld™ DP-105 Clear Adhesive is supplied in a dual syringe plastic Duo-Pak cartridge as part of the EPX™ Applicator system. To use, simply insert the Duo-Pak cartridge into the EPX applicator and start the plunger into the cylinders using light pressure on the trigger. Next, remove the Duo-Pak cartridge cap and expel a small amount of adhesive to be sure both sides of the Duo-Pak cartridge are flowing evenly and freely. If automatic mixing of Part A and Part B is desired, attach the EPX mixing nozzle to the Duo-Pak cartridge and begin dispensing the adhesives. For hand mixing, expel the desired amount of adhesive and mix thoroughly. Mix approximately 15 seconds after uniform color is obtained.

For Bulk Containers

Mix thoroughly by weight or volume in the proportions specified in the Typical Uncured Properties section. Mix approximately 15 seconds after uniform color is obtained.

4. For maximum bond strength apply adhesive evenly to both surfaces to be joined.
5. Application to the substrates should be made within 3 minutes. Larger quantities and/or higher temperatures will reduce this working time.
6. Join the adhesive coated surfaces and allow to cure at 60°F (16°C) or above until completely firm. Heat up to 200°F (93°C), will speed curing. These products will cure in 48 hours @ 75°F (24°C).
7. Keep parts from moving during cure. Contact pressure is necessary. Maximum shear strength is obtained with a 3-5 mil bond line.
8. Excess uncured adhesive can be cleaned up with ketone type solvents.*

Adhesive Coverage: A 0.005 in. thick bondline will yield a coverage of 320 sq. ft./gallon.

***Note:** When using solvents, extinguish all ignition sources and follow the

Surface Preparation

For high strength structural bonds, paint, oxide films, oils, dust, mold release agents and all other surface contaminants must be completely removed. However, the amount of surface preparation directly depends on the required bond strength and the environmental aging resistance desired by the user.

The following cleaning methods are suggested for common surfaces:

Steel:

1. Wipe free of dust with oil-free solvent such as acetone, isopropyl or alcohol solvents.*
2. Sandblast or abrade using clean fine grit abrasives.
3. Wipe again with solvent to remove loose particles.
4. If a primer is used, it should be applied within 4 hours after surface preparation. If Scotch-Weld 1945 B/A two-part primer is used, apply a thin coating (0.5 mils) on the metal surfaces to be bonded, air dry for 10 minutes, then cure for 30 minutes at 180°F (82°C) prior to bonding.

Aluminum:

1. Vapor Degrease: Perchloroethylene condensing vapors for 5-10 minutes.
2. Alkaline Degrease: Oakite 164 solution (9-11 oz./gallon water) at 190°F ± 10°F (88°C ± 5°C) for 10-20 minutes. Rinse immediately in large quantities of cold running water.
3. Acid Etch: Place panels in the following solution for 10 minutes at 150°F ± 5°F (66°C ± 2°C).

Sodium Dichromate	4.1 - 4.9 oz./gallon
Sulfuric Acid, 66°Be	38.5 - 41.5 oz./gallon
2024-T3 aluminum (dissolved)	0.2 oz./gallon minimum
Tap Water	Balance of volume
4. Rinse: Rinse panels in clean running tap water.
5. Dry: Air dry 15 minutes; force dry 10 minutes at 150°F ± 10°F (66°C ± 5°C).
6. If primer is to be used, it should be applied within 4 hours after surface preparation.

Plastics/Rubber:

1. Wipe with isopropyl alcohol.*
2. Abrade using fine grit abrasives.
3. Wipe with isopropyl alcohol.*

Glass:

1. Solvent wipe surface using acetone or MEK.*
2. Apply a thin coating (0.0001 in. or less) of primer such as Scotch-Weld EC-3901 Primer to the glass surfaces to be bonded and allow the primer to dry before bonding.

***Note:** When using solvents, extinguish all ignition sources and follow the manufacturer's precautions and directions for use.

Scotch-Weld™

Epoxy Adhesives

DP-105 Clear

Surface Preparation (continued)

- For small or intermittent applications the EPX applicator is a convenient method of application.
- For larger applications, these products may be applied by use of flow equipment.
- Two part meter/mixing/dispensing equipment is available for intermittent or production line use. These systems may be desirable because of their variable shot size and flow rate characteristics and are adaptable to many applications.

Test Procedures

1. Viscosity determined using AdhD TM (Adhesives Division, Test Method.) C-1d. Procedure involves Brookfield RVF, #7 spindle, 20 rpm and 80°F (27°C). Measurement taken after 1 minute rotation.
2. Worklife determined using AdhD TM C-3180. Procedure involves periodically measuring a 2 gram mixed mass for self-leveling and wetting properties. This time will also approximate the usable worklife in an EPX mixing nozzle.
3. Tack-free determined per AdhD TM C-3173. Involves dispensing 0.5 gram amount of adhesive onto substrate and testing periodically for no adhesive transfer to metal spatula.
4. Handling strength determined per AdhD TM C-3179. Time to handling strength taken to be that required to achieve a 50 psi OLS strength using aluminum substrates.
5. The cure time is defined as that time required for the adhesive to achieve a minimum of 80% of the ultimate strength as measured by aluminum-aluminum OLS.
6. Tensile and Elongation. Used procedure in AdhD C-3094/ASTM D 882. Samples were 2" dumbbells with .0125" neck and .030" sample thickness. Separation rate was 2 inches per minute. Samples cured 2 hrs RT plus 2 hrs/160°F (71°C).
7. Weight loss by TGA reported as that temperature at which 5% weight loss occurs by TGA in air at 5°C (4°F) rise per minute per ASTM 1131-86.
8. TCE determined using Dupont TMA Analyzer using a heating rate of 50°F (10°C) per minute. Second heat values given.
9. Glass Transition Temperature (T_g) determined using Perkin Elmer DSC Analyzer with a heating rate of 68°F (20°C) per minute. Second heat values given.
10. Thermal conductivity determined using ASTM C177 and C-matic Instrument using 2 inch diameter samples.
11. Thermal shock resistance run per AdhD TM C-3174. Involves potting a metal washer into a 2" x 0.5" thick section and cycling this test specimen to colder and colder temperatures.
12. Overlap shear (OLS) strengths were measured on 1" wide 1/2" overlap specimens. These bonds were made individually using 1" x 4" pieces of substrate. The thickness of the bond line was 0.005-0.008". All strengths were measured at 70°F (21°C) except where noted. (Test per ASTM D 1002-72.)

The separation rate of the testing jaws was 0.1" per minute for metals, 2" per minute for plastics and 20" per minute for rubbers. The thickness of the substrates were: steel, 0.060"; other metals, 0.05-0.064"; rubber, 0.125"; plastics, 0.125".

Scotch-Weld™

Epoxy Adhesives

DP-105 Clear

Test Procedures (continued)

13. T-peel strengths were measured on 1" wide bonds at 73°F (23°C). The testing jaw separation rate was 20 inches per minute. The substrates were 0.020" thick. (Tests per ASTM D 1876-61T).
14. Solvent resistance was determined using cured (24 hrs RT + 2hrs 160°F [71°C]) samples (1/2" x 4" x 1/8" thickness) immersed in the test solvent for 1 hour and 1 month. After the allotted period of time the sample was removed and visually examined for surface attack as compared to the control.

Key: A - Unaffected - no change to color or surface texture.
B - Slight attack - noticeable swelling of surface.
C - Moderate/severe attack - extreme swelling of surface.
15. Exotherm determined using the stated mass mixed for 1 minute and then by electronic thermocouple measuring the peak temperature and time to that temperature.

Precautionary Information

Refer to Product Label and Material Safety Data Sheet for Health and Safety Information before using the product.

Storage and Shelf Life

Store products at 60-80°F (15-27°C) for maximum shelf life. These products have a shelf life of 2 years in their unopened containers and 15 months in Duo-Pak containers.

For Additional Information

To request additional product information or to arrange for sales assistance, call toll free 1-800-362-3550. Address correspondence to: 3M Adhesives Division, 3M Center, Building 220-7E-05, St. Paul, MN 55144-1000. Our fax number is 651-733-9175. In Canada, phone: 1-800-364-3577. In Puerto Rico, phone: 1-787-750-3000. In Mexico, phone: 5-270-2180.

Important Notice

3M MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. User is responsible for determining whether the 3M product is fit for a particular purpose and suitable for user's method of application. Please remember that many factors can affect the use and performance of a 3M Adhesives Division product in a particular application. The materials to be bonded with the product, the surface preparation of those materials, the product selected for use, the conditions in which the product is used, and the time and environmental conditions in which the product is expected to perform are among the many factors that can affect the use and performance of a 3M product. Given the variety of factors that can affect the use and performance of a 3M product, some of which are uniquely within the user's knowledge and control, it is essential that the user evaluate the 3M product to determine whether it is fit for a particular purpose and suitable for the user's method of application.

Limitation of Remedies and Liability

If the 3M product is proved to be defective, THE EXCLUSIVE REMEDY, AT 3M'S OPTION, SHALL BE TO REFUND THE PURCHASE PRICE OF OR TO REPAIR OR REPLACE THE DEFECTIVE 3M PRODUCT. 3M shall not otherwise be liable for loss or damages, whether direct, indirect, special, incidental, or consequential, regardless of the legal theory asserted, including negligence, warranty, or strict liability.

ISO 9002

This Adhesives Division product was manufactured under a 3M quality system registered to ISO 9002 standards.

For Additional Product Safety and Health Information, See Material Safety Data Sheet, or call:

3M

Adhesives Division

3M Center, Building 220-7E-05
St. Paul, MN 55144-1000
Phone: 1-800-364-3577 or 651/737-6501



Recycled Paper
40% pre-consumer
10% post-consumer

Printed in U.S.A.
©3M 1998 78-6900-9675-1